No AFSH Natalia Vasquez NSPS 0000a

NSPS SUBPART OOOOa ANNUAL REPORT

SWEDEN VALLEY 102

Potter County, Pennsylvania

MAR 2 9 2018

March 2018

Prepared for:



JKLM Energy, LLC 2200 Georgetowne Drive Suite 500 Sewickley, Pennsylvania 15143

Prepared by:



Aptim Environmental & Infrastructure, Inc. 500 Penn Center Boulevard Suite 1000 Pittsburgh, Pennsylvania 15235

Table of Contents

1.	General Information	1
2.	Well Information	1
3.	Centrifugal Compressor	1
4.	Reciprocating Compressor	1
5.	Pneumatic Controller	
6.	Storage Vessel	2
7.1	Fugitive Emissions Components – Survey 1	2
7.2	Fugitive Emissions Components – Survey 2	2
8.	Pneumatic Pump	3
9.	Closed Vent System Certification	3

List of Attachments

Attachment 1 Certification Statement

1. General Information [40 CFR 60.5420a(b)(1)]	
Requirement	Response
Company Name [(b)(1)(i)]	JKLM Energy, LLC
Facility Site Name [(b)(1)(i)]	Sweden Valley 102
US Well ID [(b)(1)(i)]	37-105-21850-00-00
Location [(b)(1)(i)]	
 Address 	See Site Location Description and Latitude/Longitude Coordinates below.
If address not available:	
Site Location Description	Facility is located off of Cherry Springs Road (Highway 44) about 5 miles south of the intersection of Cherry Springs Road with East 2 nd Street (Highway 6) in Potter County near Summit Township municipality.
 Lat/Long Coordinates (NAD 1983) 	41.71724, -77.89994
Identification of each affected facility included in report [(b)(1)(ii)]	Fugitive Components at the Well Site
Reporting Period [(b)(1)(iii)]	
Beginning Date	January 9, 2017
End Date	January 9, 2018
Certification Statement [(b)(1)(iv)]	See Attachment 1

2. Well Information [40 CFR 60.5420a(b)(2)]	
Requirement	Response
	Not Applicable. No well completion operations during the compliance period.

3. Centrifugal Compressor [40 CFR 60.5420a(b)(3)]	
Requirement	Response
	Not Applicable. No centrifugal compressors are located at this site.

4. Reciprocating Complete (40 CFR 60.5420a(b)(4)]	ressor
Requirement	Response
	Not Applicable. No reciprocating compressors are located at this site.

5. Pneumatic Controller [40 CFR 60.5420a(b)(5)]	
Requirement	Response
	Not Applicable. No applicable pneumatic controllers are located at this site.

6. Storage Vessel [40 CFR 60.5420a(b)(6)]	
Requirement	Response
	Not Applicable. No applicable storage vessels are located at this site.

Requirement	Response
Date of Survey [(b)(7)(i)]	May 23, 2017
 Time of Survey [(b)(7)(ii)] Start Time End Time 	3:31 pm 4:33 pm
 Name of operator(s) performing survey. If using OGI, note the training and experience of the operator. [(b)(7)(iii)] 	Ryan J. Flanagan. Certified OGI Thermographer through June 15, 2022, by Infrared Training Center with four years of LDAR experience.
 Ambient temperature, sky conditions, and maximum wind speed [(b)(7)(iv)] 	73.7°F; clear skies; 1.1 mph winds
 Monitoring instrument [(b)(7)(v)] 	FLIR Infrared Camera Model GF320
 Any deviations from the monitoring plan [(b)(7)(vi)] 	No
 Number and type of components where fugitive emissions were detected [(b)(7)(vii)] 	(1) One Valve; (2) Others
 Number and type of components that were not repaired [(b)(7)(viii)] 	(0) Zero
 Number and type of difficult-to-monitor and unsafe-to-monitor components monitored [(b)(7)(ix)] 	Not Applicable
 Date of successful repair of components [(b)(7)(x)] 	May 23, 2017; June 22, 2017
 Number and type of components placed on delay of repair and explanation for delay [(b)(7)(xi)] 	(0) Zero
 Type of instrument used to resurvey repaired components that could not be repaired during initial finding [(b)(7)(xii)] 	FLIR Infrared Camera Model GF320

7.2 Fugitive Emissions Components - Survey 2

[40 CFR 60.5420a(b)(7)] Response Requirement Date of Survey [(b)(7)(i)] October 10, 2017 • Time of Survey [(b)(7)(ii)] 1:34 pm o Start Time o End Time 2:32 pm Ryan J. Flanagan. Certified OGI Thermographer · Name of operator(s) performing survey. through June 15, 2022, by Infrared Training Center with If using OGI, note the training and four years of LDAR experience. experience of the operator. [(b)(7)(iii)]

Requirement	Response
Ambient temperature, sky conditions, and maximum wind speed [(b)(7)(iv)]	75.1°F; overcast skies; 5.1 mph winds
Monitoring instrument [(b)(7)(v)]	FLIR Infrared Camera Model GF320
 Any deviations from the monitoring plan [(b)(7)(vi)] 	No
Number and type of components where fugitive emissions were detected [(b)(7)(vii)]	(1) One Other
 Number and type of components that were not repaired [(b)(7)(viii)] 	(0) Zero
Number and type of difficult-to-monitor and unsafe-to-monitor components monitored [(b)(7)(ix)]	Not Applicable
 Date of successful repair of components [(b)(7)(x)] 	October 10, 2017
 Number and type of components placed on delay of repair and explanation for delay [(b)(7)(xi)] 	(0) Zero
Type of instrument used to resurvey repaired components that could not be repaired during initial finding [(b)(7)(xii)]	Not Applicable

8. Pneumatic Pump	
[40 CFR 60.5420a(b)(8)]	
Requirement	Response
•	Not Applicable. No applicable pneumatic pumps are located at this site.

9. Closed Vent System [40 CFR 60.5420a(b)(12)]	Certification
Requirement	Response
	Not Applicable. No closed vent systems are located at this site.

Attachment 1

Certification Statement

40 CFR SUBPART OOOOa ANNUAL REPORT CERTIFICATION STATEMENT

40 CFR 60.5420a(b)(1)(iv)

Based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.

Joseph M. Harrick
Printed Name
General Manager, Environmental Health and Safety
Title
Signature 4. Harris
March 28, 2018

Date